

**AIR CONDITIONING—NEW O-RING AVAILABILITY
AND APPLICATIONS—SERVICE TIP**

**Article No.
96-20-7**

FORD: 1992-1993 FESTIVA
1992-1994 TEMPO
1992-1997 PROBE, THUNDERBIRD
1992 and after ESCORT, MUSTANG, TAURUS
1994-1997 ASPIRE
1995 and after CONTOUR
1992-1996 BRONCO
1992-1997 AEROSTAR
1992 and after ECONOLINE, EXPLORER, F-150-350 SERIES, F-47, RANGER
1995 and after WINDSTAR
1992 and after F & B SERIES

LINCOLN: 1992 and after CONTINENTAL
1993-1998 MARK VIII

MERCURY: 1992-1994 TOPAZ
1992-1997 COUGAR
1992 and after SABLE, TRACER
1993-1994 CAPRI
1995 and after MYSTIQUE
1993 and after VILLAGER
1997 and after MOUNTAINEER

ISSUE

This bulletin provides climate control system O-ring part number information.

ACTION

When servicing A/C systems, refer to the following application charts for correct O-ring part numbers.

SPRING LOCK COUPLINGS AND TUBE-O FITTINGS	
Size	Part Number
3/8"	W701993-S
1/2"	W701992-S
5/8"	W701994-S
3/4"	391305-S100

PEANUT FITTINGS	
Size	Part Number
3/8"	W702643-S300
1/2"	W702645-S300
5/8"	W702647-S300
3/4"	W702649-S300

COMPONENTS	
Component	Part Number
Orifice Tube	N807115-S
FX-15/FS-10 Manifold	N806959-S
FS-6 Manifold	390697-S
Cycle Switch (R-134a and R-12)	N807083-S
High Side Charge Port and Low Side Pressure Relief Valve (PRV)	W701992-S
High Pressure Switch and Low Side Charge Port	W701993-S
High Side PRV	379737-S
FS-10 Compressor Shaft Seal	F1VY-19D665-A

The contents of O-ring Service Kit F3VY-19D690-A* are as follows:

- Two (2) 391304-S100**
- Two (2) 391305-S100
- Two (2) 391396-S100**
- Four (4) 391397-S100**

*This O-ring kit will be obsolete and new O-rings will need to be ordered separately.

Article No. 96-20-7 Cont'd.

**These Part Numbers have been replaced by new thicker O-rings. They can be used until stock is depleted. The following are replacement numbers:

- 391302-S100 replaced by W701993-S
- 391303-S100 replaced by W701992-S
- 391304-S100 replaced by W701994-S
- 391396-S100 replaced by W701993-S
- 391397-S100 replaced by W701992-S

PART NUMBER	PART NAME
W701993-S	3/8" Spring Lock Coupling And Tube-O Fittings
W701992-S	1/2" Spring Lock Coupling And Tube-O Fittings
W701994-S	5/8" Spring Lock Coupling And Tube-O Fittings
391305-S100	3/4" Spring Lock Coupling And Tube-O Fittings
F3VY-19D690-A	O-Ring Service Kit (See Description In This Article)

OTHER APPLICABLE ARTICLES: 95-2-2

WARRANTY STATUS: INFORMATION ONLY

OASIS CODES: 208000, 208200, 208999